BROTHER TN-315 Printer Fuser Jamming Elimination

1. Make sure your toners are full.
2. On the machine, go to [Menu, General Setup, Ecology and press OK](#).
3. Select Toner Save, select Yes and press OK.
4. Go back to [Menu, Printer, Calibration and press OK](#).
5. Choose Calibrate and press OK.
6. Let the machine go through its cycle.
7. Go to the BROTHER Print Manager in whatever program you are trying to print from.
8. Go to Properties, then go to Settings.
9. In the new window that will pop up, again select Settings.
10. Then, on the bottom Saturation bar, adjust for minimum saturation.
11. This last step may need to be repeated on any new documents created within your program.
12. These three steps will reduce the color toner usage and will eliminate any fuser separation/jamming issues.