

Konica Minolta C35

Meter/Counter Report Instructions

1. Press Utilities/Counter
2. Press User Setting
3. Press Print Setting
4. Press Print Reports
5. Press Configuration Page
6. Press Print
7. Press OK